IMPORTANT NOTE ABOUT THE ADQ-CDI-TCU/1 HAT SERIES

The following items should not be used for new projects:

ADQ-CDI-TCU/1 1.2 (Item number: 231953)

The replacement parts are supplied from stock.
In addition, replacement is guaranteed.

To replace the ADQ-CDI-TCU/1 1.2, please order the following items::

ADQ-CDI-TCU/1 1.4 (Item number: 243219)
ADQ-CDI-TCU/1 EXT1 (Item number: 243220)

All further technical information can be found in the manual.
3D STEP data will be provided to you as usual.




Figure: ADQ-CDI-TCU/1 1.4



Figure: ADQ-CDI-TCU/1 EXT1

IMPORTANT NOTE ABOUT THE ADQ-CDI-TCU/1 HAT SERIES

Upgrading from ADQ-CDI-TCU/1 1.2 to ADQ-CDI-TCU/1 1.4 with ADQ-CDI-TCU/1 EXT1




Figure: ADQ-CDI-TCU/1 1.2

= identical




Figure: ADQ-CDI-TCU/1 1.4 mit ADQ-CDI-TCU/1 EXT1

Please refer to the manuals for all technical information regarding the pin assignments of the respective modules.

Note: Note: The pin assignments and layout of the ADQ-CDI-TCU/1 1.2 board are identical to the ADQ-CDI-TCU/1 1.4 board. There is also another 5-pin connector on the board. This connector is not relevant for replacement.

IMPORTANT NOTE ABOUT THE ADQ-CDI-TCU/1 HAT SERIES

Presentation of the new ADQ-CDI-TCU/1 EXT2 Plug-in Board

ADQ-CDI-TCU/1 EXT2 (Item number: 246958)




Figure: ADQ-CDI-TCU/1 EXT2 incl. Pin Assignment

All further technical information can be found in the manual.
3D STEP data will be provided to you as usual.

IMPORTANT NOTE ABOUT THE ADQ-CDI-TCU/1 HAT SERIES

The following item is not longer available (End of life):

ADQ-CDI-TCU/1 1.2 (Item number: 231953)

The supply of spare parts is ensured from stock.
In addition, replacement is ensured.

Please order the following items to replace the ADQ-CDI-TCU/1 1.2:

ADQ-CDI-TCU/1 1.4 (Item number: 243219)
ADQ-CDI-TCU/1 EXT1 (Item number: 243220)

All further technical information can be found in the manual.
3D STEP data will be provided to you as usual.




Figure: ADQ-CDI-TCU/1 1.4



Figure: ADQ-CDI-TCU/1 EXT1

IMPORTANT NOTE ABOUT THE ADQ-CDI-TCU/1 HAT SERIES

Replacement of an ADQ-CDI-TCU/1 1.2 with ADQ-CDI-TCU/1 1.4 using ADQ-CDI-TCU/1 EXT1




Figure: ADQ-CDI-TCU/1 1.2

= identical




Figure: ADQ-CDI-TCU/1 1.4 with ADQ-CDI-TCU/1 EXT1

All technical information regarding the pin assignments of the respective assemblies can be found in the manuals.

Note: The pin assignments and layout on the ADQ-CDI-TCU/1 1.2 assembly are identical to the ADQ-CDI-TCU/1 1.4 assembly. Additionally, there is another 5-pin connector on the assembly. This is not relevant for the replacement.

IMPORTANT NOTE ABOUT THE ADQ-CDI-TCU/1 HAT SERIES

Presentation of the new ADQ-CDI-TCU/1 EXT2 extension board

ADQ-CDI-TCU/1 EXT2 (Item number: 246958)




Figure: ADQ-CDI-TCU/1 EXT2 including pin assignment

All further technical information can be found in the manual.
3D STEP data will be provided to you as usual.

IMPORTANT NOTE ABOUT THE ADQ-CDI-TCU/1 HAT SERIES

Presentation of the new ADQ-CDI-TCU/1 EXT3 extension board

ADQ-CDI-TCU/1 EXT3 (Item number: 267898)




Figure: ADQ-CDI-TCU/1 EXT3 including pin assignment

All further technical information can be found in the manual.
3D STEP data will be provided to you as usual.